SECRET

Declassification Review by NGA/DoD

OUT55626

S E C R E T 932021Z

1965 MAY 3 20 30**z**

CyNo. 1

25X1

Recic

- CAMERA B 101 WAS USED IN MISSION 8014 FLOWN 29 APRIL 1965. PROCESSING WAS ACCOMPLISHED BY BARKSDALE.
 - 2. ORIGINAL NEGATIVE:
- A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD WHERE NOT DEGRADED BY VEHICLE MANOUVERS AND/OR ATMOSPHERIC CONDITIONS.
- B. 9R SIDE: BOTH EDGES CONTAIN FINE EDGE FOG AND SMALL STATIC DISCHARGES. THE INBOARD EDGE ALSO CONTAINS INTERMITTENTER MINOR ROLLER INDUCED STATIC DISCHARGES.
- C. 9L SIDE: MINOR STATIC DISCHARGES ARE PRESENT INTERMIT TENTLY ON BOTH EDGES. THE INBOARD EDGE CONTAINS ROLLER INDUCED STATIC DISCHARGES THROUGHOUT THE FIRST HALF OF THE MISSION RECORD. FRAMES 1006 TO 1012 ARE CREASED. FRAMES 1019 TO 1023 ALSO CONTAIN CREASES. A MANUFACTURER'S SPLICE I PRESENT IN FRAME 729.
 - D. BOTH SIDES: THE TITLED FRAMES ARE NUMBERED 0000 TO 2351
- E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES.
 - 3. POSITIVE:
- THE PI SUITABILITY RANGES FROM FAIR TO GOOD. DEGRADATION IS DUE PRIMARILY TO VEHICLE MANOUVERS AND HAZE.
 - B. THE PRINTING AND PROCESSING ARE GOOD.
 - C. THE CLOUD COVER IS APPROXIMATELY 25 PERCENT.

SECRET

-- END OF MESSAGE--

GROUP 1 ed from automatic persoling and

25X1